

# Oil Field Environmental Incident Summary

**Incident:** 20131014091309      **Date/Time of Notice:** 10/14/2013 09:01

**Responsible Party:** Oasis Petroleum North America LLC

**Well Operator:** OASIS PETROLEUM NORTH AMERICA LLC

**Well Name:**

**Field Name:**

**Well File #:** 0

**Date Incident:** 10/10/2013      **Time Incident:** 12:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 156

**Rng:** 102

**Sec:** 22

**Qtr:** NE NE

**Location Description:** Pipeline leak on Fresh Water System

**Submitted By:** Dennis Stevens

**Received By:**

**Contact Person:**

5437 137Ave NW  
Williston, ND 58802

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 4 Miles

**Distance Nearest Water Well:** 4 Miles

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** No

**Reported to NRC:** Yes

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0	barrels	0	barrels		
<b>Brine</b>	0	barrels	0	barrels		
<b>Other</b>	500	barrels	0	barrels		

**Description of Other Released Contaminant:**

Fresh water

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

1/2 mile down county right of way

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

dug up and repaired fuse and back filled (10-14-13 Keith, Dan Grafton called me last week Thursday and said they had a SW spill at the Erickson SWD. I had Dan Wells check it out he thought it appeared to be FW. Dan Wells said Dan Grafton was going to get a water sample was it FW? We have not heard anything.) (10-14-13 Call from Darwin Stevens he is going to try to get water analysis from Dan Grafton.) (10-14-13 Text from Keith Oylow Yes it was FW will have Dan call you ASAP.) Call from Dan Grafton at about 2:00 PM said they had tested the water and TDS was between 498 and 600)

**Wastes Disposal Location:** N/A

**Agencies Involved:** Joh Axtman

**Updates**

---

**Date:** 10/15/2013 **Status:** Inspection

**Author:** Miller, Adam

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Inspected site. Pipeline has been excavated, repaired and reburied. Soil at bottom of hill is very saturated but that could be attributed to recent rains. Soil conductivity readings are about 500 microSiemens at the surface and 1500 to 2000 microSiemens at 18 inches of depth. It appears that only fresh water was spilled. Landowner has been notified of incident but has yet to visit location.

---

**Date:** 9/13/2016 **Status:** Inspection

**Author:** Kangas, Kathleen

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On site at 11:00 a.m. 47 degrees, sunny, wind 2 mph NNW. Directly south of Erickson SWD in Sec 15 SE SE. Looking south into NE NE of Section 22, it appears cultivated/cropland. No areas of bare soil observed. Didn't enter property further due to posted sign.